Docket No. 034942-000245 (formerly 110619CFB.US)

In the Drawings

The attached replacement and annotated sheet(s) of drawings include changes to FIG. 1 and FIG. 2 as follows:

FIG. 1 has been amended such that box 121 has been relabeled 139 for consistency with the specification, and the descriptive legend has been changed from "chordic converter" to "cordic converter" to thereby correct the misspelling.


FIG. 2 has been amended to re-route the connection 237 to the delay element 238, and to insert cordic converter 139 of FIG. 1 in its proper place for consistency with FIG. 1 and the remainder of the description.

Attachment: Replacement Sheet


Annotated Sheet Showing Changes


TRP Docket No.: 034942-245
Annotated Sheet Showing Changes

w sep o q



Robert E. Krebs, Thelen Reid & Priest, LLP Serial No.: 09/885,811 Filed: June 19, 2001 TRP Docket No.: 034942-245 Replacement Sheet





ROBERT E. KREBS, THELEN REID & PRIEST LLP
Serial No.: 09/885,811
Filed: June 19, 2001
TRP DOCKET NO.: 034942-245
Replacement Sheet

